

YOUR BREATHING OUR EXPERTISE

SUNDSTRÖM COMPETENCE CENTRE srsafety.com

PROBLEM

Beard

To get perfect fit with a tight fitting mask you need to be clean shaved on daily basis. If you have beard, moustache or side burns another type of respirator is required.



Facial hair, such as beards, moustaches and sideburns, reduce the level of protection offered by tight-fitting respirators, and create a need for Powered Air Respiratory Protection to ensure adequate levels of contaminant reduction.

National regulations and requirements must be followed, as these may vary from country to country. Check carefully which regulations apply.

Sundström recommends

Heavier workload and higher dust concentrations and for users that are clean shaven and with facial hair, beard or sideburns.



Fan unit SR 700 or SR 500.



SR 580 Helmet with visor or SR 570 face shield with or without bump cap depending on work situation.



