




SR 500

SYSTEM OVERVIEW



| No. | Description | Name | Art No. |
|-----|-----------------------------------------|------------|----------|
| 1. | Fan unit | SR 500 | R06-0121 |
| 2. | Chemical cartridge CL/HC/SD/FM/AM/MA | SR 533 | H02-7221 |
| 3. | Chemical cartridge OV/SD/CL/HC/HF | SR 532 | H02-7121 |
| 4. | Filter adapter | SR 511 | R06-0105 |
| 5. | P100/HE Particulate filter | SR 510 | H02-1321 |
| 6. | HE Particulate filter | SR 710 | H02-1521 |
| 7. | Pre-filter holder | | R01-0605 |
| 8. | Pre-filter holder | SR 512 | R06-0106 |
| 9. | Asbestos kit | SR 509 | T06-0105 |
| 10. | Battery HD 3.5 Ah | SR 502 | T06-0101 |
| 11. | Battery charger | SR 513 | R06-0122 |
| 12. | Hood | SR 520 S/M | H06-0321 |
| | Hood | SR 520 M/L | H06-0221 |
| 13. | Hood | SR 530 | H06-0421 |
| 14. | Hood | SR 602 | H06-5521 |
| 15. | Face shield | SR 570 | H06-6521 |

| No. | Description | Name | Art No. |
|-----|---------------------------------------|----------------------------------|----------------------------------|
| 16. | Helmet with visor | SR 580 | H06-8021 |
| 17. | Helmet with visor / Welding shield | SR 580 / SR 584 | H06-8321 |
| 18. | Full face mask, PC visor | SR 200 | H01-1221 |
| | Full face mask, glass visor | SR 200 | H01-1321 |
| 19. | Breathing hose 0,9 m PU | SR 550 | T01-1216 |
| | Breathing hose 0,7 m rubber | SR 551 | T01-1218 |
| 20. | Half mask | SR 900 S SR 900 M SR 900 L | H01-3021 H01-3121 H01-3221 |
| 21. | Single Hose | SR 951 | T01-3010 |
| 22. | Twin Hose | SR 952 | R01-3013 |
| 23. | Harness | SR 552 | T06-0116 |
| 24. | Belt cotton | SR 508 | R06-0101 |
| 25. | Belt leather | SR 503 | T06-0103 |
| | Belt leather, Large | SR 503L | T06-0107 |
| 26. | Belt rubber | SR 504 | T06-0104 |
| 27. | Flow meter | SR 356 | R03-0346 |

